Harding Lawson Associates

A Report Prepared for

United States Navy Western Division Naval Facilities Engineering Command P.O. Box 727 San Bruno, California 94066-0720

BUILDING 123 INVESTIGATION NAVAL STATION, TREASURE ISLAND HUNTERS POINT ANNEX SAN FRANCISCO, CALIFORNIA

HLA Job No. 02176,159.02

by

John D. Skalbeck Staff Geologist II

Glenn S. Goodman

Senior Hydrogeologist

Harding Lawson Associates 7655 Redwood Boulevard P.O. Box 578 Novato, California 94948 415/892-0821

November 2, 1988

TABLE OF CONTENTS

LIST	OF TABLES	iii
LIST	OF ILLUSTRATIONS	iii
1.0	INTRODUCTION	1
2.0	FIELD INVESTIGATION	3
3.0	CHEMICAL ANALYSES AND RESULTS	4
4.0	DISCUSSION	5
5.0	RECOMMENDATIONS	6
6.0	REFERENCES	7
ILLUSTRAT	IONS	
Appendix	LABORATORY REPORTS AND CHAIN OF CUSTODY FORM	
DISTRIBUTI	ON	

G4500-R ii

LIST OF TABLES

Table 1 Selected Building 123 - Battery and Electroplating Shop Investigation Analytical Results

LIST OF ILLUSTRATIONS

Plate 1 Location Map

Plate 2 Site Map

G4500-R

1.0 INTRODUCTION

This report presents the results of Harding Lawson Associates' (HLA) investigation of Building 123 at the Naval Station, Treasure Island, Hunters Point Annex (HPA), San Francisco, California (Plate 1).

The Fence to Fence Hazardous Material Survey (ERM-WEST, 1988) conducted at HPA identified locations that are suspect of possible environmental contamination. A sump inside Building 123 that may contain oily fluids was identified by the Navy as one such area. Characterization of the sump fluids is necessary to assess appropriate methods for disposal of the sump fluid. From 1946 to 1974, the Navy used this building as a battery shop. Waste acids, metals, and plating shop wastes (chlorinate, cyanide, and electrolytes) were generated at this site. Subsequent to 1974 and prior to 1986, Triple A Machine Shop leased the building to Mann Endless Cassettes. Mann Endless Cassettes used the facility as a warehouse. Since 1986, the building has been leased by the Navy to All Make Auto, First Metal and Chemical, and Sunray Trucking. These recent tenants use the facility as a storage and distribution warehouse.

The objectives of this investigation were to: 1) verify the existence of contamination in the sump; 2) assess whether an immediate threat to public health or the environment exists; and 3) identify potential response actions, if any, that might mitigate possible hazards at Building 123. However, because of the limited scope of work for this investigation, definitive interpretation of the analytical results with respect to the assessment of the threat to public health and the environment and the formulation of response actions is limited. The results presented herein provide a preliminary screening of conditions existing at the Building 123 sump site at the time of sampling, and are limited to those areas in the immediate vicinity of the sampling locations. The area of investigation is shown on Plate 2.

G4500-R 1 of 7

The scope of the investigation consisted of collecting and analyzing two sludge samples from a sump inside Building 123 and preparing this report. The sump is approximately 3 feet wide, 5 feet long, and 2 feet deep. Approximately 1.5 feet of fluid was found in the sump.

G4500-R 2 of 7

2.0 FIELD INVESTIGATION

Two sludge samples were collected on May 17, 1988 from a sump in the north central portion of Building 123 (Plate 2). The sump is approximately 3 feet wide, 5 feet long and 2 feet deep. Approximately 1.5 feet of fluid was found in the sump.

HLA personnel were equipped with Level D personal protective equipment upon site entry (Section 7.0, Site Safety Plan (SSP); HLA 1988a). Health and safety monitoring of the breathing zone was performed during sample collection. Readings in the breathing zone did not exceed background levels (1 to 2 ppm); however, strong organic odors were detected by the sampling crew within the immediate vicinity of the sump. At this time, Level C protective equipment was donned according the the HPA SSP (HLA, 1988a).

Sludge samples were collected from two locations inside the sump (Plate 2) using a dedicated clean, glass jar secured with dedicated nylon cord. The jar was lowered to the sump bottom at each sampling location. The jars were then retrieved and the recovered sludge was poured directly from the glass jar to the appropriate laboratory-supplied sample container for the specified analyses. The sample containers were labeled and stored in an ice chest containing blue ice (cooled to approximately 4°C) until they were delivered to the laboratory at the end of the day.

A field blank (OCO4) was prepared at the HLA field office at HPA by decanting deionized water from a clean glass pint jar into the appropriate laboratory-supplied sample containers for the specified analyses.

Chain of custody forms were completed in the field as specified in Section 13.0 of the Quality Assurance Project Plan (QAPP) (HLA, 1988b) and the samples were delivered to the analytical laboratory, Curtis and Tompkins, LTD., at the end of the day.

G4500-R 3 of 7

4 of 7

3.0 CHEMICAL ANALYSES AND RESULTS

The two sludge samples collected from the sump in Building 123 and the field blank were analyzed for priority pollutant metals (ICP Test Method 6010) and for organochlorine pesticides and PCBs (EPA Test Method 608). PCBs and Organochlorine pesticides were not detected in either sample. Metals were detected in both sludge samples. The most notable metals detected were antimony, arsenic, barium, cadmium, chromium-total, copper, lead, molybdenum, nickel, selenium, and zinc. The blank sample (0C04) contained low levels of nickel and zinc. The pH of the samples ranged from 7.3 to 7.4. Table 1 summarizes those analytes detected. The laboratory reports and the chain of custody form are presented in Appendix A.

G4500-R

4.0 DISCUSSION

On the basis of the analyses conducted at the Building 123 sump, the material in the sump appears to pose no immediate threat to human health and/or the environment. No PCBs were detected on the sump sludge; however, low levels of metals were detected. The metals concentrations from these anlayses are below the Total Threshold Concentration (TTLC) Values (State of California, 1985). It is not known if the sump is leaking or discharging liquids to the soil and/or ground water or to drains within Building 123. The sump was covered by an open mesh steel grate. This cover could allow tenants working inside the building to come into contact with the sump liquid. In addition, a large engine block was located directly on top of and adjacent to the sump. The engine block appeared to be in the process of being cleaned or drained and had metal filings and oily material surrounding its base.

During the site investigation, a second sump was observed inside Building 123 approximately 20 feet north of the sampled sump. This second sump was also filled with liquid; however, machinery obstructed access to the second sump.

G4500-R 5 of 7

5.0 RECOMMENDATIONS

We recommend that the sludge/fluid material in the sump at Building 123 be further characterized for TPH and oil and grease, removed, and properly disposed by a licensed waste disposal contractor in a timely manner. Once the sump is empty, the sump walls should be cleaned and inspected for leaks/cracks that may provide pathways for the sump liquid to enter the surrounding soils or ground water. The second sump inside Building 123 should also be characterized so that the liquid inside it can be removed and the sump can be inspected. Personnel working within the building (employees of All Make Auto, First Metal and Chemical, and Sunray Trucking) may have the potential for dermal exposure to the material in these sumps.

Activities such as engine block cleaning in the vicinity of the sump or oil disposal into the sump should cease as soon as possible. Because this site is part of the ongoing Remedial Investigation (RI) at HPA, (IR-10, the Battery and Electroplating Shop), a full characterization of soils, floor drains, and ground water at the site is not necessary at this time but is included in the RI. The data collected during this investigation should be reviewed and considered during the RI.

G4500-R 6 of 7

6.0 REFERENCES

- ERM WEST, 1988. Fence to Fence Hazardous Material Survey, Naval Station, Treasure Island, Hunters Point Annex, San Francisco, California. July 1988.
- HLA, 1988a. Site Safety Plan, Naval Station, Treasure Island, Hunters Point Annex, San Francisco, California. January 14.
- HLA, 1988b. Quality Assurance Project Plan (QAPP), Naval Station, Treasure Island, Hunters Point Annex, San Francisco, California. May 26.
- State of California, 1985. Title 22, California Administrative Code, Section 66699.

G4500-R 7 of 7

TABLES

Table 1. Selected Building 123-Battery and Electroplating Shop Investigation Analytical Results

CAM 17 Metals in Soils and Wastes Digestion Method: EPA 3050


Metal	Detection Limit (mg/kg)	BE01	mples BE02 (mg/kg)	Detection Limit (mg/l)	Field Blank (OCO4) (mg/l)	Method
Antimony	3.0	5.0	ND	0.2	ND	EPA 7040
Arsenic	2.0	4.0	5.0	0.1	ND	EPA 6010
Barium	5.0	18	12	0.2	ND	EPA 7080
Beryllium	0.5	ND	ND	0.02	ND	EPA 7090
Cadmium	0.3	3.9	2.0	0.01	ND	EPA 6010
Chromium (total)	0.5	2.8	2.7	0.02	ND	EPA 6010
Cobalt	0.5	ND	155	0.02	ND	EPA 6010
Copper	0.5	77	26	0.02	ND	EPA 6010
Lead	3.0	135	140	0.2	ND	EPA 6010
Mercury	0.1	ND	ND	0.001	ND	EPA 7470
Molybdenum	0.5	20	2.3	0.02	ND	EPA 6010
Nickel	0.5	ND	3.7	0.02	0.09	EPA 6010
Selenium	3.0	3.5	3.3	0.2	ND	EPA 6010
Silver	1.0	ND	ND	0.05	ND	EPA 6010
Thallium	3.0	ND	ND	0.2	ND	EPA 7840
Vanadium	0.5	ND	ND	0.2	ND	EPA 6010
Zinc	0.5	470	360	0.01	0.03	EPA 6010

ND = Not detected.

mg/l = milligrams per liter

mg/kg = milligrams per kilogram

ILLUSTRATIONS





Harding Lawson Associates Engineers and Geoscientists


Location Map HPA Building 123 **Hunters Point Annex** San Francisco, California

DRAWN ML

JOB NUMBER 2176,159.02 APPROLE

REVISED 6/88

DATE



DRAWN COB NUMBER APPROVED DATE REVISED DATE

ML 2176,159.02 6/88

Appendix A LABORATORY REPORT AND CHAIN OF CUSTODY

APPENDIX A LABORATORY REPORT AND CHAIN OF CUSTODY

BUILDING 123 INVESTIGATION

THE ABOVE IDENTIFIED APPENDIX HAS MISSING PAGES. IT COULD NOT BE DETERMINED WHETHER THESE PAGES ARE MISSING OR THE APPENDIX WAS ISSUED WITHOUT THESE PAGES.

QUESTIONS MAY BE DIRECTED TO:

DIANE C. SILVA
RECORDS MANAGEMENT SPECIALIST
SOUTHWEST DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
1220 PACIFIC HIGHWAY
SAN DIEGO, CA 92132

TELEPHONE: (619) 532-3676



LABORATORY NUMBER: 14724

CLIENT: HARDING LAWSON ASSOCIATES

JOB #: 2176,159/163/160.02,

HUNTERS POINT

DATE RECEIVED: 05/17/88

DATE ANALYZED: 05/18/88

DATE REPORTED: 06/01/88

PAGE 2 OF 34

			=========		
	C&T ID:	14724-3	14724-4	14724-5	14724-9
PARAMETER	SAMPLE ID:	8899PH01	8899PH02	8899PH03	8899OC04
pH, SU EPA 9040		7.3	7.4	7.4	5.5
1111 JO40					
CYANIDE, mg/L SMWW 412J		ND(0.05)	ND(0.05)	ND(0.05)	ND(0.05)
SULFIDE, mg/L SMWW 427D		6.5	ND(1)	ND(1)	ND(1)
OIL & GREASE, m	ng/L	ND(20)	ND(20)	ND(20)	ND(20)

ND = NONE DETECTED. LIMIT OF DETECTION IS INDICATED IN PARENTHESES.



CLIENT: Harding Lawson Associates

SAMPLE ID: 8899BE01

HLA Job #: 2176,159/163/160.02

HUNTERS POINT

DATE RECEIVED: 05/17/88
DATE ANALYZED: 05/24,27/88

DATE REPORTED: 06/01/88

PAGE 3 OF 34

CAM 17 Metals in Soils & Wastes Digestion Method: EPA 3050

METAL	RESULT	DETECTION LIMIT	METHOD
	mg/Kg	mg/Kg	
Antimony	5.0	3.0	EPA 7040
Arsenic	4.0	2.0	EPA 6010
Barium	18	5.0	EPA 7080
Beryllium	ND	0.5	EPA 7090
Cadmium	3.9	0.3	EPA 6010
Chromium (total)	2.8	0.5	EPA 6010
Cobalt	ND	0.5	EPA 6010
Copper	77	0.5	EPA 6010
Lead	135	3.0	EPA 6010
Mercury	ND	0.1	EPA 7470
Molybdenum	20	0.5	EPA 6010
Nickel	ND	0.5	EPA 6010
Selenium	3.5	3.0	EPA 6010
Silver	ND	1.0	EPA 6010
Thallium	ND	3.0	EPA 7840
Vanadium	ND	0.5	EPA 6010
Zinc	470	0.5	EPA 6010

ND = None Detected

	%RPD	%SPIKE		%RPD	%SPIKE	
Antimony	<1	115	Mercury	<1	105	
Arsenic	19	105	Molybdenum	18	99	
Barium	26	99	Nickel	15	92	
Beryllium	<1	100	Selenium	17	115	
Cadmium	15	80	Silver	<1	84	
Chromium	22	80	Thallium	<1	125	
Cobalt	<1	86	Vanadium	26	92	
Copper	13	87	Zinc	9	82	
Lead	11	82				



CLIENT: Harding Lawson Associates

SAMPLE ID: 8899BE02

HLA Job #: 2176,159/163/160.02

HUNTERS POINT

DATE RECEIVED: 05/17/88
DATE ANALYZED: 05/24,27/88

DATE REPORTED: 06/01/88

PAGE 4 OF 34

CAM 17 Metals in Soils & Wastes Digestion Method: EPA 3050

METAL	RESULT	DETECTION LIMIT	METHOD
	mg/Kg	mg/Kg	
Antimony	ND	3.0	EPA 7040
Arsenic	5.0	2.0	EPA 6010
Barium	12	5.0	EPA 7080
Beryllium	ND	0.5	EPA 7090
Cadmium	2.0	0.3	EPA 6010
Chromium (total)	2.7	0.5	EPA 6010
Cobalt	155	0.5	EPA 6010
Copper	26	0.5	EPA 6010
Lead	140	3.0	EPA 6010
Mercury	ND	0.1	EPA 7470
Molybdenum	2.3	0.5	EPA 6010
Nickel	3.7	0.5	EPA 6010
Selenium	3.3	3.0	EPA 6010
Silver	ND	1.0	EPA 6010
Thallium	ND	3.0	EPA 7840
Vanadium	ND	0.5	EPA 6010
Zinc	360	0.5	EPA 6010

ND = None Detected

	%RPD	*SPIKE		 %RPD	%SPIKE
Antimony	<1	115	Mercury	<1	105
Arsenic	19	105	Molybdenum	18	99
Barium	26	99	Nickel	15	92
Beryllium	<1	100	Selenium	17	115
Cadmium	15	80	Silver	<1	84
Chromium	22	80	Thallium	<1	125
Cobalt	<1	86	Vanadium	26	92
Copper	13	87	Zinc	9	82
Lead	11	82			



LAB NUMBER: 14724-9

CLIENT: HARDING LAWSON ASSOCIATES JOB #: 2176,159/163/160.02, H. P. SAMPLE ID: 88990C04

DATE RECEIVED: 05/17/88 DATE ANALYZED: 05/24,27/88

DATE REPORTED: 06/01/88

PAGE 11 OF 34

CAM 17 Metals in Aqueous Solutions

METAL	RESULT	DETECTION LIMIT	METHOD
	mg/L	mg/L	
Antimony	ND	0.2	EPA 7040
Arsenic	ND	0.1	EPA 6010
Barium	ND	0.2	EPA 7080
Beryllium	ND	0.02	EPA 7090
Cadmium	ND	0.01	EPA 6010
Chromium (total)	ND	0.02	EPA 6010
Cobalt	ND	0.02	EPA 6010
Copper	ND	0.02	EPA 6010
Lead	ND	0.2	EPA 6010
Mercury	ND	0.001	EPA 7470
Molybdenum	ND	0.02	EPA 6010
Nickel	0.09	0.02	EPA 6010
Selenium	ND	0.2	EPA 6010
Silver	ND	0.05	EPA 6010
Thallium	ND	0.2	EPA 7840
Vanadium	ND	0.02	EPA 6010
Zinc	0.03	0.01	EPA 6010

ND = None Detected

		~-~				
	%RPD	%SPIKE		%RPD	%SPIKE	
Antimony .	<1	115	Mercury	<1	89	
Arsenic	4	94	Molybdenum	6	9 8	
Barium	31	109	Nickel	20	91	
Beryllium	<1	100	Selenium	1	100	
Cadmium	6	96	Silver	17	84	
Chromium	<1	90	Thallium	<1	125	
Cobalt	<1	88	Vanadium	8	91	
Copper	5	91	Zinc	4	99	
Lead	8	9.0			•	



CLIENT: Harding Lawson Associates

HLA Job #: 2176,159/163/160.02, HUNTERS POINT CLIENT ID: 88990C04

DATE RECEIVED: 05/17/88 DATE EXTRACTED: 05/23/88 DATE ANALYZED: 05/24/88 DATE REPORTED: 06/01/88

Page 18 of 34

EPA METHOD 625: BASE/NEUTRAL AND ACID EXTRACTABLES IN WATER EXTRACTION METHOD: EPA 3510 LIQUID/LIQUID

2-Chlorophenol	ACID COMPOUNDS	RESULT ug/L	LOD ug/L
Bis(2-chloroethyl)ether 1,3-Dichlorobenzene 1,4-Dichlorobenzene ND 1,2-Dichlorobenzene ND Bis(2-chloroisopropyl)ether N-nitrosodi-n-propylamine Hexachloroethane ND Nitrobenzene Isophorone Bis(2-chloroethoxy)methane 1,2,4-Trichlorobenzene ND Naphthalene Hexachlorocyclopentadiene 2-Chloronaphthalene Dimethyl phthalate Acenaphthylene 2,6-Dinitrotoluene ND SE ND ND ND SE ND ND ND ND ND ND ND ND ND N	2-Chlorophenol 2-Nitrophenol 2,4-Dimethylphenol 2,4-Dichlorophenol 4-Chloro-3-methylphenol 2,4,6-Trichlorophenol 2,4-Dinitrophenol 4-Nitrophenol 2-Methyl-4,6-dinitrophenol	ND ND ND ND ND ND ND ND	5 25 5 10 5 25 25 25 25
1,3-Dichlorobenzene 1,4-Dichlorobenzene 1,2-Dichlorobenzene Bis(2-chloroisopropyl)ether ND N-nitrosodi-n-propylamine ND Nitrobenzene ND Nitrobenzene ND Sis(2-chloroethoxy)methane ND Nisophorone ND Naphthalene ND Naphthalene ND Hexachlorocyclopentadiene ND Dimethyl phthalate ND Acenaphthene	BASE/NEUTRAL COMPOUNDS		
4-Chlorophenylphenyl ether ND	1,3-Dichlorobenzene 1,4-Dichlorobenzene 1,2-Dichlorobenzene Bis(2-chloroisopropyl)ether N-nitrosodi-n-propylamine Hexachloroethane Nitrobenzene Isophorone Bis(2-chloroethoxy)methane 1,2,4-Trichlorobenzene Naphthalene Hexachlorobutadiene Hexachlorocyclopentadiene 2-Chloronaphthalene Dimethyl phthalate Acenaphthylene 2,6-Dinitrotoluene Acenaphthene 2,4-Dinitrotoluene Fluorene Diethyl phthalate 4-Chlorophenylphenyl ether	ND N	555555555555555555555555555555555555555



LABORATORY NUMBER: 14724-9 EPA 625
CLIENT ID: 88990C04 page 19 of 34

BASE/NEUTRAL COMPOUNDS	RESULT ug/L	LOD ug/L
Hexachlorobenzene	ND	5
Phenanthrene	ND	5
Anthracene	ND	
Dibutylphthalate	ND	5 5 5
Fluoranthene	ND	5
Benzidine	ND	25
Pyrene	ND	
Butylbenzylphthalate	ND	5 5
Benzo (a) anthracene	ND	5
3,3'-Dichlorobenzidine	ND	25
Chrysene	ND	5
Bis (2-ethylhexyl)phthalate	N D	5
Di-n-octyl phthalate	N D	5
Benzo (b) fluoranthene	ND	5
Benzo (k) fluoranthene	ND	5
Benzo (a) pyrene	ND	5
Indeno (1,2,3-cd) pyrene	ND	25
Dibenzo (a,h) anthracene	N D	25
Benzo (ghi) perylene	N D	25
HSL COMPOUNDS		
Benzoic Acid	ND	50
2-Methylphenol	ND	5
4-Methylphenol	ND	5
2,4,5-Trichlorophenol	ND	5
Aniline	ND	5
Benzyl Alcohol	ND	25
4-Chloroaniline	ND	10
2-Methylnaphthalene	ND	5
2-Nitroanline	N D	25
3-Nitroaniline	ND	25
Dibenzofuran	ND	5
4-Nitroaniline	ND	25

ND = None Detected, Limit of Detection (LOD) appears in far right column

Compound	% Recovery	Compound	<pre>%Recovery</pre>			
2-Fluorophenol	101	2-Fluorobiphenyl	80			
2,4,6-tribromophenol	157	Terphenyl-d14	60			
Nitrobenzene-d5	96					



CLIENT: HARDING LAWSON ASSOCIATES

JOB #: 2176,159/163/160.02, HUNTERS POINT

SAMPLE ID: 8899BE01

DATE RECEIVED: 05/17/88
DATE EXTRACTED: 06/01/88
DATE ANALYZED: 06/02/88
DATE REPORTED: 06/03/88

PAGE 26 OF 34

EPA 608: Organochlorine Pesticides and PCBs in Water Extraction Method: EPA 3510

	RESULT	DETECTION LIMIT
COMPOUND	ug/L	ug/L
alpha-BHC	ND	1
beta-BHC	ND	1
gamma-BHC	ND	1
delta-BHC	ND	1
Heptachlor	ND	1
Aldrin	ND	1
Heptachlor Epoxide	ND	1
Endosulfan I	ND	1
Dieldrin	ND	1
pp-DDE	ND	1
Endrin	ND	1
Endosulfan II	ND	1
pp-DDT	ND	1
Chlordane	ND	10
Toxaphene	ND	10
Methoxychlor	ND	10
PCB 1016	ND	10
PCB 1221	ND	10
PCB 1232	ND	10
PCB 1242	ND	10
PCB 1248	ND	10
PCB 1254	ND	10
PCB 1260	ND	10

ND = Not detected.

Duplicat	ce: Rel	lative %	Difference
Average	Spike	Recovery	r &



CLIENT: HARDING LAWSON ASSOCIATES

JOB #: 2176,159/163/160.02, HUNTERS POINT

SAMPLE ID: 8899BE02

DATE RECEIVED: 05/17/88
DATE EXTRACTED: 05/31/88
DATE ANALYZED: 06/02/88
DATE REPORTED: 06/03/88

PAGE 27 OF 34

EPA 608: Organochlorine Pesticides and PCBs in Water Extraction Method: EPA 3510

COMPOUND	RESULT	DETECTION LIMIT
COMPOUND	ug/L	ug/L
alpha-BHC	ND	1
beta-BHC	ND	1
gamma-BHC	ND	1
delta-BHC	ND	1
Heptachlor	ND	1
Aldrin	ND	1
Heptachlor Epoxide	ND	1
Endosulfan I	ND	1
Dieldrin	ND	1
PP-DDE	ND	1
Endrin	ND	1
Endosulfan II	ND	1
pp-DDT	ND	1
Chlordane	ND	10
Toxaphene	ND	10
Methoxychlor	N D	10
PCB 1016	ND	10
PCB 1221	N D	10
PCB 1232	ND	10
PCB 1242	ND	10
PCB 1248	ND	10
PCB 1254	ND	10
PCB 1260	ND	10

ND = Not detected.

QA/QC SUMMARY:

Duplicate: Relative % Difference 24
Average Spike Recovery % 89



CLIENT: HARDING LAWSON ASSOCIATES

JOB #: 2176,159/163/160.02, HUNTERS POINT

SAMPLE ID: 88990C04

DATE RECEIVED: 05/17/88
DATE EXTRACTED: 05/31/88
DATE ANALYZED: 06/01/88
DATE REPORTED: 06/03/88

PAGE 34 OF 34

EPA 608: Organochlorine Pesticides and PCBs in Water Extraction Method: EPA 3510

	RESULT	DETECTION LIMIT
COMPOUND	ug/L	ug/L
alpha-BHC	ND	0.05
beta-BHC	ND	0.05
gamma-BHC	ND	0.05
delta-BHC	ND	0.05
Heptachlor	ND	0.05
Aldrin	ND	0.05
Heptachlor Epoxide	ND	0.05
Endosulfan I	ND	0.05
Dieldrin	ND	0.05
pp-DDE	ND	0.05
Endrin	ND	0.05
Endosulfan II	ND	0.05
pp-DDT	ND	0.05
Chlordane	ND	0.5
Toxaphene	ND	0.5
Methoxychlor	ND	0.5
PCB 1016	ND	0.5
PCB 1221	ND	0.5
PCB 1232	ND	0.5
PCB 1242	ND	0.5
PCB 1248	ND	0.5
PCB 1254	ND	0.5
PCB 1260	ND	0.5

ND = Not detected.

Duplicate: Relative % Difference	24
Average Spike Recovery %	89

CHAIN C. CLUTOL, FORM

DATE

Dγ

Time

Yr

07880

Mo

1818101717

٥

Environmental Carvices Paraion ___ ...ush Lanuring Road Novato, California 94947

MATRIX

00 00 CODE 0 0 CODE 51ω 49ε Water X Soil

33 33

33

48

48

(415) 892-0821

2176, 159 Job Number: Point

Yr

SAMPLE

NUMBER

OR

LAB

NUMBER

Seq

O

04

BE

Wk

28990

Name/Location:.

Unpres. H₂ SO₄ HNO₃

5

5

Project Manager: <u>G. Good man</u>

#CONTAINERS & PRESERV.

Samplers: John SKALBECK

Recorder:

(Signature Required) STATION DESCRIPTION/ **NOTES** Bld2 123 Sump 00 House - Pump House Club officers Club officers Club - Comp Field Blank

, , , ,	EPA 601/8010	EPA 602/8020	EPA 624/8240	EPA 625/8270	Priority Piltnt. Metals \mathcal{ILC}	Benzene/Toluene/Xylene	Total Petrol. Hydrocarb.	FPA 608/8080	0:11 / 600000	Crande Sultide et	, HG4						
					X			X									
					X			X									
				×	X			×	X	×							
				×	X			×	×	×							
2				X	צ		L	×	×	×			L	L			L
				X	X			X			X			L	L	L	
	L			X	X			×			X		L	L		L	
	L			X	X		L	×		L	X	L	L	L	L		L
4	L			X	Κ			X	×	X		L	L	L	L	L	L
													L				

ANALYSIS REQUESTED

	٨	LA NUM		1			EP1		М	OL		co	A DE		MISCELLANEOUS	CHAIN OF CUSTODY RECORD				
Yr	V	Vk	_ {	eq		, F	EE	Τ	Ľ	CD	L	,				RELINQUISHED/BY: (Signature) A RECEIVED BY: (Signature) DATE/TIME				
1	$oldsymbol{\perp}$	$\bot \downarrow$	\downarrow	_	Ц	1	1	1	\downarrow	\downarrow				_		John Shalbeck	}			
	1	11	1	1		4	4	+	1	4-	Ш			_		BÉLINQUISHED BY: (Signature)	RECEIVED BY: (Signature)		DATE/TIME	
4	 	1-1	_	1		4	4	+	\bot	$oldsymbol{\perp}$		_		_		4	l			
1	\downarrow	\sqcup	4	1		4	4	-	1	\perp	Ц			_		RELINQUISHED BY: (Signature)	RECEIVED BY: (Signature) DATE/TIME		DATE/TIME	
1	\perp	\sqcup	4	1		4	1	1	\perp	\downarrow							ļ			
1	\downarrow	$\downarrow \downarrow$	\perp	1		\perp			\perp	\perp	L					RELINQUISHED BY: (Signature)	RECE	IVED BY: (Signature)	DATE/TIME	
	L		·						L								<u> </u>			
					Ц											DISPATCHED BY: (Signature) DATE/		RECEIVED FOR LABBY:	DATE/TIME	
										1							<u> </u>	1 / Will	11/11/10	
I	1	П		T					T	Τ						METHOD OF SHIPMENT		, , , ,		

DISTRIBUTION

BUILDING 123 INVESTIGATION NAVAL STATION, TREASURE ISLAND HUNTERS POINT ANNEX SAN FRANCISCO, CALIFORNIA November 2, 1988

COPY NO. <u>/</u>

		Copy No
18 copies:	United States Navy Western Division Naval Facilities Engineering Command P.O. Box 727 San Bruno, California 94066-0720 Attention: Ms. Louise Lew, Code 1146	1-18
1 copy:	Job File	19
1 copy:	QC/Bound Report File	20
1 copy:	Chronological File	21
1 copy:	Aqua Terra Technologies	22

JDS/GSG/ere/G4500-R

QUALITY CONTROL REVIEWER

Lisa S. Teague Geologist - 3839